

PLD

LARGE SIZE PRESSURE INDICATOR

DISPLAY	INPUT	OUTPUT
LED 4-Digit	4-20 mA	4-20 mA 2-Relay



SPECIFICATION

MODEL	PLD
DISPLAY	4-Digit Red LED
ACCURACY	±0.2% F.S.
SAMPLING CYCLE	200ms
INPUT	DC4-20mA
OUTPUT	None DC4-20mA+2-Relays output* 1~5VDC+2-Relays output*
SWITCH DATA	DC24V-1A, AC120V-1A, AC240V-0.5A
AMBIENT TEMPERATURE	-10 to 60℃
HOUSING MATERIAL	Steel
POWER	AC110 / 220V, 50~60Hz
FEATURE	Adjustable Scale & Decimal Point Peak Hold Correction of error Adjustable Dead Band [2-digit] Built in power supply for transmitter [DC24V]
MOUNTING	Panel mounting Type


ACCESSORY

Panel Mounting Bracket
고정 브라켓 (기본 포함)




DIMENSION (mm)

※ 제품의 사양에 따라 변경 될 수 있습니다



Ordering Information



| FLOW | | PRESSURE | | TEMPERATURE | | AC | | DC | | BATTERY | | OUTPUT | | CONTACT | | DISPLAY |

RELATED PRODUCTS

Pressure Transmitter 압력센서, 압력변

▶ 12V Pressure / 압력센서, 압력변

TST-02 압력센서 0~20bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~20bar	TST-03 압력센서 0~30bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~30bar	PHI 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar
PT100 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	PT100 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	PHI 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar
TST-04 압력센서 0~20bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~20bar	211A 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	SL1 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar
SMD 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar		

Flush Diaphragm Transmitter 압력센서, 압력변

▶ 12V Pressure / 압력센서, 압력변

PHD 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	CST 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	PT100000 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar
PHD00-S 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	PHD00-S 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	

Corrosion Resistance Transmitter 압력센서, 압력변, 내부부식

▶ 12V Pressure / 압력센서, 압력변, 내부부식

SP12-F 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	SP12-T 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	AT15 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar
SD12-PS 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	SD12-TS 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	DT14 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar
DT123 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar		

Pressure Transmitter with Display 압력센서, 압력변

▶ 12V Pressure / 압력센서, 압력변

SP10 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	SP10 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	LT10 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar
PHD00 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	PHD00 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	PHD00 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar
PHD00 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	SD12-PS 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	SD12-TS 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar

Explosion Proof Transmitter 압력센서, 압력변

▶ 12V Pressure / 압력센서, 압력변

PHD00EX 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	PHD00EX 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	PHD00EX 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar
PHD00EX 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	PHD00EX 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	

Diff. Pressure Transmitter 차압센서, 차압변, 압력변

▶ 12V Pressure / 압력센서, 압력변, 차압

PHD00EX 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	PHD00EX 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	PHD00EX 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar
PHD00EX 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	PHD00EX 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar	PHD00EX 압력센서 0~10bar (0.1%FS) 출력: 4~20mA 정밀도: ±0.1%FS 온도: 0~50°C 압력: 0~10bar